

COMMONLY USED CONVERSIONS

Multiply	By	To Obtain	Multiply	By	To Obtain
Inches	25.4	Millimeters	Cubic Inches	16.38716	Cubic Centimeters
Millimeters	0.03937	Inches	Liters	61.023	Cubic Inches

Common Inch Oversizes Converted to Millimeters		Ring Width Conversion Chart		
Decimal Inches	Millimeters	Decimal	Metric	Fraction
.005"	0.127	0.039	1.00	
.010"	0.254	0.047	1.20	3/64"
.020"	0.508	0.055		
.030"	0.762	0.059	1.50	
.040"	1.016	0.063	1.59	1/16"
.050"	1.270	0.069	1.75	
.060"	1.524	0.070		
Common Millimeter Oversizes Converted to Inches		0.075		
		0.078	1.98	5/64"
0.20	.008"	0.079	2.00	
0.25	.010"	0.080	2.20	
0.40	.016"	0.094	2.38	3/32"
0.50	.020"	0.098	2.50	
0.60	.024"	0.110	2.80	
0.75	.030"	0.118	3.00	
0.80	.032"	0.125	3.18	1/8"
1.00	.040"	0.138	3.50	
1.20	.047"	0.156	3.97	5/32"
1.40	.055"	0.157	4.00	
1.50	.059"	0.177	4.50	
1.60	.063"	0.188	4.75	3/16"
1.75	.069"	0.197	5.00	
2.00	.079"	0.219	5.55	7/32"
3.00	.118"	0.236	6.00	
4.00	.157"	0.250	6.35	1/4"
		0.313	7.94	5/16"
		0.375	9.53	3/8"

